



Sixteen holes tapped for 8-32 screws, located with respect to the center of the plate.

$\phi$  0.003

Twelve clearance holes, 8 for 8-32 screws and 4 for 10-32 screws, located with respect to the center of the plate.

$\phi$  0.003

Tenn. State Univ.	
CASS 2-m AST Project	
04/30/98	J.A.E.
AST-05-R20	