



This drawing gives locations of the radial stiffening ribs and of holes cut into the top of the skirt to clear drive motors and lines of the fork. See drawing AST-01-R08 for the location of the access holes in the outside edge of the skirt. Assume symmetry for locations of features not explicitly located.