



This drawing gives locations of the hole cut into the side of the skirt to clear the drive tractor unit. See drawing AST-01-R07 for the location of hole in the top of the skirt for the motors. Tolerances are ± 0.03 inches.