



Location of an axial hard point

Axial-Support Levers

Possible locations of mirror-support levers in the mirror cell (tube). Some of these are obviously better orientations than others. Clearances must be left for the axial hard points and for the attachments for the azimuth drive sector.

Inappropriate orientations of support levers

Attachment for altitude drive sector

Tenn. State Univ.	
CASS 2-m AST Project	
02/23/97	J.A.E.
AST-06-A04	