



Location of an axial hard point

Axial-Support Levers

Possible locations of mirror-support levers in the mirror cell (tube). Some of these are obviously better orientations than others. Clearances must be left for the axial hard points and for attachments for the azimuth drive sector.

Force No.	Units
87#	4
90#	2
94#	10
95#	2
98#	4
99#	2
104#	8
108#	4

Tenn. State Univ.
CASS 2-m AST Project
 08/31/99 J.A.E.
 AST-06-A04a