



Axial Support & Hard Point

Application of axial support lever to back of primary mirror. (36 positions) See drawing AST-06-A01.

Application of axial hard point to back of primary mirror. (3 positions) See drawing AST-06-A06 for details.

Tenn. State Univ.	
CASS 2-m AST Project	
04/14/97	AST-06-A05
J.A.E.	