



Machining Secondary Mirror Cell, 2

Clearance hole for motor shaft. The dimension is not critical.

Four clearance holes for 10-32 screws

Four holes tapped for 10-32 (to mount motor standoffs, part 7-044)

Tenn. State Univ.	
CASS 2-m AST Project	
02/11/98	J.A.F.
AST-07-R06	