



Tenn. State Univ.	
CASS 2-m AST Project	
02/20/97	AST-11-A08
J.A.E.	

Application of mirror lifting fixtures. The part shown in drawing AST-11-A01 is permanently fixed in the cell. To lift the mirror, remove the instrument head, attach the spanner to the lifting fixture with 5/8-inch threaded rods, attach a crane with the 1-inch lifting eye, detach lateral supports, various hard points, and retainers from the mirror, and lift with the crane.