



Main Input Stage		
No.	Qty.	Description
19	1	Threaded attachment for fibers, type 1
18	1	Threaded attachment for fibers, type 1
17	6	1/4-20x1/2 sckt-hd cap screw (stainless)
16b	2	no. 6 lock washer
16a	2	6-32x3/8 sckt-hd cap screw (stainless)
15	6	4-40x1/4 sckt-hd cap screw (stainless)
14b	2	8-32x3/4 sckt-hd cap screw (stainless)
14a	4	8-32x1/2 sckt-hd cap screw (stainless)
13	2	Limit switches (HTM FCU1-00401N-A3U2/1)
12s	2	2-56x3/32 set screw
12	1	Holder for limit switch, back
11	1	Holder for limit switch, front
10	1	Arm to attach motor to slide
9	1	no. 4 lock washer
8	1	no. 4 flat washer
7	1	4-40 nut
6	1	Motor mount
5	1	Linear stepper motor (HSI 46441-12)
4	1	Alignment jig
3	1	Right-angle Bracket
2	1	Slider body
1	1	Linear slide (Automation Gauges VA-11)

Tenn. State Univ.
CASS 2-m AST Project
 07/30/02 J.A.E. AST-21-A02