



Low-Dispersion Input Stage		
No.	Qty.	Description
58	4	1/4-20x1/2 skt-head cap screw (stainless)
57	1	no. 3 lock washer
56	1	3-48x1/4 skt-head cap screw (stainless)
55	1	Clamp for fiber end
54	2	no. 6 lock washer
53	2	6-32x3/8 skt-head cap screw (stainless)
52	6	4-40x1/4 skt-head cap screw (stainless)
51b	2	8-32x3/8 skt-head cap screw (stainless)
51a	4	8-32x1/4 skt-head cap screw (stainless)
50	2	Limit switches (HTM FCU1-D0401N-A3U2/1)
49	1	Holder for limit switch, back
48	1	Holder for limit switch, front
47	1	Arm to attach motor to slide
46	1	4-40 lock washer
45	1	4-40 nut
44	1	Motor mount
43	1	Linear stepper motor (HSI 48441-12)
42	1	Base
41	1	Slider body
40	1	Linear slide (Automation Gauges WA-11)
No.	Qty.	Description

Tenn. State Univ.  
**CASS** 2-m AST Project  
 07/30/02 J.A.E. AST-21-A05