



Inner Stiffeners for Fork

Part 3-009

Part 3-008

Part 3-004, Lateral Base Stiffener.
 1/2-inch aluminum plate. Tolerances for the
 10-in ventilation holes are 0.25 inches in
 both position and radius (2 reqd)

Parts 3-008 and 3-009, Lower and Upper
 Tyne Stiffeners. 1/2-inch aluminum plate.
 Tolerances for the 10-in ventilation holes
 are 0.25 inches in both position and radius
 (4 of each reqd)

Tenn. State Univ.	
CASS 2-m AST Project	
11/18/97	AST-03-P06
J.A.E.	