



Assembly of Fork, 4

Step 4. Add tyne top plates, parts 3-010.

Step 2. Add lower tyne stiffeners, parts 3-008.

Step 1. Add base top plate, part 3-007.

Step 3. Add upper tyne stiffeners, parts 3-009.

1 2 3 4 5 6 7 8

D C B A

Tenn. State Univ. CASS 2-m AST Project

01/17/97 J.A.E.

AST-03-R04

1 2 3 4 5 6 7 8