



Note: One of these Altitude Drive Attachments is required for the telescope. Parts are given in AST-10-P04 & P05 and machining in AST-10-P05 & R05.

No.	Qty.	Description
31	10	3/8-16x1.5 hex-head cap screw (stainless)
30	2	3/8-16x8 socket-head cap screw (stainless)
29	2	3/8-16x5 socket-head cap screw (stainless)
28	2	3/8-16x3 socket-head cap screw (stainless)
27	20	3/8-16x2 socket-head cap screw (stainless)
26	1	Flexure for altitude tractor
25	1	Attachment Block for altitude tractor/flexure
24	1	Top stiffener
23	1	Back stiffener
22	1	Front Bumper
21	2	Upright
20	1	Base plate

Tenn. State Univ.	
CASS 2-m AST Project	
03/20/97	AST-10-A04
J.A.E.	

Altitude Drive Attachment