



Azimuth Slider Hardware

Four clearance holes for M12 screws
 $\varnothing 0.003$ E F

Four clearance holes for 3/8-inch screws
 $\varnothing 0.003$ B C

Weld part 10-094 to 11-093 with 1/2-inch butt weld, grind welds and rough edges smooth, machine back flat, then machine holes as shown. Tolerances are ± 0.02 except as noted.

Weld part 10-091 to 11-090 with 1/2-inch butt weld, grind welds and rough edges smooth, machine back flat, then machine holes as shown. Tolerances are ± 0.02 except as noted.

Tenn. State Univ.	
CASS 2-m AST Project	
07/09/97	J.A.F.
AST-10-R06	