



The two cylinders must have the tolerances specified in the top and bottom 0.6 inches for mounting bearings. The inner part of the bore should be smooth, possibly slightly larger. Datum A represents the top surface of the part.