



This drawing shows locations of holes in the tractor body. The square holes on the two drive cylinder housings (parts 10-041) are equivalent to an R50 cylinder with its center located 51.75 inches from the centers of the drive-cylinder housings. Tolerance is  $\pm 0.02$  unless otherwise stated.

Tenn. State Univ.	
CASS 2-m AST Project	
08/14/97	AST-10-R09
J.A.E.	