



Jack for lifting telescope off oil pads for disaster maintenance. Make four. Part numbers listed are for one unit.

Telescope-Lifting Jack

No.	Qty.	Description
280	4	1/2-13x2.75 acct-hd cap screw
289	1	Force Point for Fork
288	1	Screw for Jack (1-10 Acme thread)
287	3	Screws for 11-285
285	1	Flange for 11-285
285	1	Bronze Nut (1-10 Acme)
284	1	Top Plate
283	4	Stiffener
282	1	Main Shaft
281	1	Feet
261	1	Base plate

No.	Qty.	Description
Tenn. State Univ.		
CASS 2-m AST Project		
07/29/02	J.A.E.	AST-11-A13

1 2 3 4 5 6 7 8

A B C D